



## \* IMPORTANT INFORMATION RELATED TO THE DANIAMANT BNWAS BW-800 \*

*(please read carefully)*

*Slangerup, January 15<sup>th</sup>, 2018*

1. The Daniamant A/S BNWAS (Bridge Navigational Watch Alarms System) BW-800 system will no longer hold the Module B type approval certificate as it is not tested and approved to the latest and revised standards.
2. **However, already installed systems may be maintained according to the requirements applicable at the time of the original installation. It is the certificate onboard that apply to the installation onboard until it is decided to replace the old system with a new installation.**
3. Daniamant will therefore still be able to supply BW-800 and the system's individual parts – as long as stock last – for maintenance, repair, replacement and/or other exchanges to existing BW-800 installations which may require this.
4. It is the sole responsibility of the Buyer to secure that installation of BW-800 or the individual parts comply to section 3 above.
5. Daniamant A/S cannot be held liable for any consequential loss, loss of profits or other indirect loss suffered by the Buyer as a result of the supplied subject of sale.
6. Any claims made to Daniamant A/S can never exceed the amount invoiced for the sold item in question.